



Blackcomb Helicopters 1850 Airport Rd Building 50 Pemberton, B.C. V0N 2L0 Attn: Taylor  
 Lovering / Isabel Peters stores@blackcombhelicopters.com

Ph. Office: 604-894-5153

Fax: 604-938-1706

www.blackcombhelicopters.com

**Actions**

- Cal - Calibration
- Che - Check
- Che - Check and  
Calibrate
- Che - Check with  
Removal
- Det - Detailed Check
- Hyd - Hydrostatic
- Ins - Inspect and  
Lubricate
- Ins - Inspection
- On - On Condition
- Ove - Overhaul
- Rep - Replacement
- Ret - Retirement
- Rew - Reweigh

**C-GUNL Detailed View**

Registration C-GUNL Date Aug 1, 2023  
 Make Eurocopter TTAF 2758.00  
 Model EC130 B4 Serial No. 4690

| Cycles values |       |            |          |            |         |                |         |
|---------------|-------|------------|----------|------------|---------|----------------|---------|
| Cycle Name    | Value | Cycle Name | Value    | Cycle Name | Value   | Cycle Name     | Value   |
| HOOK HOURS    | 2.5   | Landings   | 11 291.0 | NG CYCLES  | 7 172.9 | NP / NF CYCLES | 3 855.5 |

**Components**

| Component/Action  | Make/Model | Part No. | Serial No. | Tracking No. | Limit              | Perf.                  | Time at Inst. | Due                    | TTSC              | TTSN | Rem.               |
|---|------------|----------|------------|--------------|--------------------|------------------------|---------------|------------------------|-------------------|------|--------------------|
| 150 hr / 6 Month Blade Pins (600 Hour - BHLPL interval 150 Hour/6 Month) (AMM 62-11-00, 3-3) / Ins 6210<br>Tolerance ±10% | Airbus/    |          |            |              | 150.00H<br>6.00M   | 2756.60H<br>Jul 25, 23 |               | 2906.60H<br>Jan 25, 24 | 1.40H<br>0.20M    |      | 148.60H<br>5.80M   |
| 2400 hr / 72 Month Oil Temperature Warning System (AMM 63-42-00, 5-1/5-2) / Che 6340<br>Tolerance ±10%                    | Airbus/    |          |            |              | 2400.00H<br>72.00M | 2247.60H<br>Jan 28, 21 |               | 4647.60H<br>Jan 28, 27 | 510.40H<br>30.10M |      | 1889.60H<br>41.90M |
| 2500 hr / 72 Month Intermediate structure/Tail boom coupling / Ins 5300   | Airbus/    |          |            |              | 2500.00H<br>72.00M | 2247.60H<br>Jan 28, 21 |               | 4747.60H<br>Jan 28, 27 | 510.40H<br>30.10M |      | 1989.60H<br>41.90M |
| 3000 Hr / 72 Month Laminat Suspension Block Supports (AMM 63-31-00, 6-2) / Che 6330                                       | Airbus/    |          |            |              | 3000.00H<br>72.00M | 2242.60H<br>Nov 2, 20  |               | 5242.60H<br>Nov 2, 26  | 515.40H<br>32.97M |      | 2484.60H<br>39.03M |
| 3000 Hr / 72 Month Laminat Suspension Blocks (AMM 63-31-00, 6-1) / Che 6330   | Airbus/    |          |            |              | 3000.00H<br>72.00M | 2242.60H<br>Nov 2, 20  |               | 5242.60H<br>Nov 2, 26  | 515.40H<br>32.97M |      | 2484.60H<br>39.03M |
| 3000 Hr / 72 Month Laminat Suspension Blocks - Attachment Bolts (AMM 63-31-00, 6-3) / Che                                 | Airbus/    |          |            |              | 3000.00H<br>72.00M | 2242.60H<br>Nov 2, 20  |               | 5242.60H<br>Nov 2, 26  | 515.40H<br>32.97M |      | 2484.60H<br>39.03M |

**Components**

| Component/Action   | Make/Model                      | Part No.       | Serial No.   | Tracking No. | Limit                | Perf.                              | Time at Inst.   | Due                   | TTSC                    | TTSN | Rem.                 |
|--|---------------------------------|----------------|--------------|--------------|----------------------|------------------------------------|-----------------|-----------------------|-------------------------|------|----------------------|
| 6330<br>3000 hr / 72 Month MGB<br>Suspension Cross<br>Bar / Che<br>6300<br>Cycle Name : Landings<br>Tolerance ±10% | Airbus/                         | 350A38-1040-20 | L1514        | 41333        | 3000.00H<br>60000.0C | 2756.60H<br>Jul 25, 23<br>11275.0C | 0.00H<br>0.00   | 5756.60H<br>71275.0C  | 1.40H<br>0.20M<br>16.0C |      | 2998.60H<br>59984.0C |
| 3000 hr / 72 Month Spring-<br>Type Vibration<br>Damper / Che<br>6220<br>Tolerance ±10%                             | Airbus/                         | 350A31-0033-06 | SD1132       |              | 3000.00H<br>72.00M   | 2242.80H<br>Dec 5, 20              |                 | 5242.80H<br>Dec 5, 26 | 515.20H<br>31.87M       |      | 2484.80H<br>40.13M   |
| 600 hr / 12 Month<br>TFM/TDFM (BHP<br>Requirement) / Che<br>2300<br>Tolerance ±25%                                 | Technosonic/<br>TFM138B/TDFM136 |                |              |              | 600.00H              | 2316.70H<br>Jul 28, 21             |                 | 2916.70H              | 441.30H<br>24.10M       |      | 158.70H              |
| <b>Altimetry Devices /<br/>3100</b>  | /                               |                |              |              |                      |                                    |                 |                       |                         |      |                      |
| ► Altimetry Devices / Che<br>3100  | CAR 625 Appendix C (13)/        | 5934PD3A624    | 472251       |              | 24.00M               | 2670.20H<br>Oct 18, 22             |                 | Oct 18, 24            | 87.80H<br>9.43M         |      | 14.57M               |
| ► Transponder / Encoder /<br>Che<br>3100   | CAR 625 Appendix C (14)/        |                |              |              | 24.00M               | 2670.20H<br>Oct 18, 22             |                 | Oct 18, 24            | 87.80H<br>9.43M         |      | 14.57M               |
| Compass Swing / Cal<br>3400  | /                               |                |              |              | 12.00M               | 2757.70H<br>Jul 31, 23             |                 | Jul 31, 24            | 0.30H<br>0.00M          |      | 12.00M               |
| <b>Emergency Equipment /</b>   | /                               |                |              |              |                      |                                    |                 |                       |                         |      |                      |
| ► 12 Month First Aid Kit / Ins<br>2560   | /<br>AOSH Type 'A'              |                |              |              | 12.00M               | 2756.60H<br>Jul 25, 23             |                 | Jul 25, 24            | 1.40H<br>0.20M          |      | 11.80M               |
| ► 12 Month Survival Kit / Ins<br>2560  | Braidner/                       | FE6A           | A212A-130B   |              | 12.00M               | 2757.70H<br>Jul 31, 23             |                 | Jul 31, 24            | 0.30H<br>0.00M          |      | 12.00M               |
| ► Cabin Fire Extinguisher /<br>Hyd<br>2560   | Amerex/                         | C352           | X-983720     |              | 144.00M              | Nov 12, 14                         |                 | Nov 12, 26            | 104.63M                 |      | 39.37M               |
| ► ELT / Ins<br>2560  | /                               | S1822502-02    | 2621038-0045 | 34639        | *                    | 2718.90H<br>Jan 30, 23 *           | 0.00H<br>0.00 * | Jan 24, 25 *          | 39.10H<br>6.03M*        | *    | 17.77M*              |

Components

| Component/Action   | Make/Model                | Part No.          | Serial No.   | Tracking No. | Limit                       | Perf.                      | Time at Inst.      | Due                           | TTSC                        | TTSN               | Rem.                     |
|--|---------------------------|-------------------|--------------|--------------|-----------------------------|----------------------------|--------------------|-------------------------------|-----------------------------|--------------------|--------------------------|
| Energy Absorption Front Seats (AMM 25-21-00, 6-7) / Det 2520         | SICMA/159                 |                   |              |              | 1800.00H                    | 1733.00H<br>Jan 19, 19     |                    | 3533.00H                      | 1025.00H<br>54.40M          |                    | 775.00H                  |
| Energy Absorption Front Seats - Rails (AMM 25-21-00, 6-2) / Det 2520 | SICMA/159                 |                   |              |              | 2400.00H                    | 2756.60H<br>Jul 25, 23     |                    | 5156.60H                      | 1.40H<br>0.20M              |                    | 2398.60H                 |
| <b>Engine / Ove 7200</b>   | <b>Safran/ Arriel 2B1</b> | <b>0292005410</b> | <b>46245</b> |              | <b>3500.00H<br/>180.00M</b> | <b>0.00H<br/>Feb 1, 09</b> |                    | <b>3500.00H<br/>Feb 1, 24</b> | <b>2758.00H<br/>174.00M</b> | <b>2758.00H</b>    | <b>742.00H<br/>6.00M</b> |
| ► ECU / On 7200  | TRIUMPH/115430-07A1-7000  | 70BMF11000        | 9APM0243     | 31512        |                             | 536.80H<br>Mar 31, 15      | 1880.10H           |                               | 4101.30H<br>100.00M         | 4101.30H           |                          |
| ► Freewheel Shaft Assembly / Ove 7200                                | Safran/ Arriel 2          | 0292900020        |              |              |                             | 0.00H<br>Oct 10, 08        |                    |                               | 2758.00H<br>177.70M         | 2758.00H           |                          |
| ► Fuel Valve Assembly / Ove 7200                                     | Safran/ Arriel 2          | 0292950090        | 191          |              | 3000.00H                    | 0.00H                      |                    | 3000.00H                      | 2758.00H                    |                    | 242.00H                  |
| ► M01 - Accessory Gearbox / Ove 7200                                 | Safran/ Arriel 2          | 70BM012010        | 6413         |              | 3500.00H                    | 0.00H<br>Nov 1, 08         |                    | 3500.00H                      | 2758.00H<br>177.00M         |                    | 742.00H                  |
| ► M02 - Axial Compressor / Ove 7200                                  | Safran/ Arriel 2          | 70BM022010        | 7624         |              | 3500.00H                    | 0.00H<br>Nov 1, 08         |                    | 3500.00H                      | 2758.00H<br>177.00M         |                    | 742.00H                  |
| ► M03 - Gas Generator / Ove 7200                                     | Safran/                   | 70BM032030        | 9824         | 44537        | 3500.00H<br>180.00M         | 2405.40H<br>Mar 31, 22     | 2405.40H<br>155.70 | 3500.00H<br>Apr 9, 24         | 2758.00H<br>171.70M         | 2758.00H           | 742.00H<br>8.27M         |
| ► M04 - Free Turbine / Ove 7200                                      | Safran/ Arriel 2          | 70BM041720        | 6581         |              | 3500.00H                    | 0.00H<br>Nov 1, 08         |                    | 3500.00H                      | 2758.00H<br>177.00M         |                    | 742.00H                  |
| ► M05 - Reduction Gearbox / Ove 7200                                 | Safran/ Arriel 2          | 70BM052000        | 10518        |              | 3500.00H                    | 0.00H<br>Nov 1, 08         |                    | 3500.00H                      | 2758.00H<br>177.00M         |                    | 742.00H                  |
| ► Pump/Metering Valve assembly / Ove 7200                            | Safran/                   | 0292862620        | 715B         | 41473        | 3000.00H<br>120.00M         | 2074.20H<br>Sep 28, 19     | 1740.73H<br>38.80  | 3333.47H<br>Jul 4, 26         | 2424.53H<br>84.90M          | 2424.53H<br>84.90M | 575.47H<br>35.10M        |
| Fuel Pump / On   | Zenith-Aviation SA/       | 704A44510042      | D70856       |              |                             | 0.00H                      |                    |                               | 2758.00H                    |                    |                          |

Components

| Component/Action  | Make/Model                   | Part No.       | Serial No. | Tracking No. | Limit               | Perf.                    | Time at Inst. | Due                     | TTSC                | TTSN     | Rem.               |
|---|------------------------------|----------------|------------|--------------|---------------------|--------------------------|---------------|-------------------------|---------------------|----------|--------------------|
| 2820  | P94B12-209                   |                |            |              |                     |                          |               |                         |                     |          |                    |
| Hermetic Fire Detector 3500 Hour Inspection / Che 2600 Tolerance ±10% | Airbus/                      |                |            |              | 3500.00H            | 0.00H                    |               | 3500.00H                | 2758.00H            |          | 742.00H            |
| Hydraulic Filter Replacement / Rep 2900                               | /                            |                |            |              | 1200.00H<br>48.00M  | 2268.90H<br>May 12, 21   |               | 3468.90H<br>May 12, 25  | 489.10H<br>26.63M   |          | 710.90H<br>21.37M  |
| Hydraulic Fluid Drain & Fill / Ins 2900                               | Airbus/                      |                |            |              | 3000.00H<br>48.00M  | 2247.60H<br>Jan 28, 21   |               | 5247.60H<br>Jan 28, 25  | 510.40H<br>30.10M   |          | 2489.60H<br>17.90M |
| Hydraulic Pump / On 6310  | JTEKT HPI/                   | 704A34-3100-06 | 30614430   |              |                     | 451.70H<br>Nov 12, 14    |               |                         | 2306.30H<br>104.63M | 2306.30H |                    |
| Hydraulic Pump - Poly "V" Belt / Ret 6310                             | Airbus/                      | POLYV597K4     |            | 41996        | 1800.00H<br>72.00M  | 2247.60H<br>Jan 28, 21   |               | 4047.60H<br>Jan 28, 27  | 510.40H<br>30.10M   |          | 1289.60H<br>41.90M |
| Hydraulic Pump Drive Bearing / Ret 2900                               | /                            | 593733         | R/NA14193  | 45075        | 3600.00H<br>72.00M* | 2405.40H<br>Mar 31, 22 * | *             | 6005.40H<br>Jan 1, 24 * | 352.60H<br>16.00M*  | *        | 3247.40H<br>5.00M* |
| <b>Kits /</b>   | <b>/</b>                     |                |            |              |                     |                          |               |                         |                     |          |                    |
| ▶ 100 hr / 12 Month Airbus Litter Kit / Ins 2500                      | Airbus/<br>SH02-45           | ICA-ECL-119    |            |              | 100.00H<br>12.00M   | 2746.40H<br>Mar 16, 23   |               | 2846.40H<br>Mar 16, 24  | 11.60H<br>4.50M     |          | 88.40H<br>7.50M    |
| ▶ 100 hr Airbus Cowling Maintenance Steps / Ins 5300                  | Airbus/<br>SH02-38           | ICA-ECL-112    |            |              | 100.00H             | 2746.40H<br>Mar 16, 23   |               | 2846.40H                | 11.60H<br>4.50M     |          | 88.40H             |
| ▶ 12 Month Mygoflight I-Pad Mount & Cradle / Ins 2500                 | MyGoFlight/                  |                |            |              | 12.00M              | 2413.00H<br>Apr 21, 22   |               | Apr 21, 23              | 345.00H<br>15.33M   |          | -3.33M             |
| ▶ 150 hr / 12 Month Airbus Cargo Pods / Ins 2500                      | Airbus/<br>SH03-33           | ICA-ECL-123    |            |              | 150.00H<br>12.00M   | 2670.60H<br>Oct 22, 22   |               | 2820.60H<br>Oct 22, 23  | 87.40H<br>9.30M     |          | 62.60H<br>2.70M    |
| ▶ 150 hr / 12 Month Airbus Interior Modifications / Ins 2500          | Airbus/<br>STC O-LSH14-120/D | ICA-AHCA-288   |            |              | 150.00H<br>12.00M   | 2670.60H<br>Oct 22, 22   |               | 2820.60H<br>Oct 22, 23  | 87.40H<br>9.30M     |          | 62.60H<br>2.70M    |

**Components**

| Component/Action                                | Make/Model                    | Part No.       | Serial No. | Tracking No. | Limit               | Perf.                  | Time at Inst. | Due                    | TTSC                | TTSN     | Rem.               |
|---|-------------------------------|----------------|------------|--------------|---------------------|------------------------|---------------|------------------------|---------------------|----------|--------------------|
| ▶ 300 hr Dart Bearpaw Inspection / Ins 3200     | Dart/<br>SH93-4               | ICA-D130-700   | B127019    |              | 300.00H             | 2536.70H<br>Aug 4, 22  |               | 2836.70H               | 221.30H<br>11.90M   |          | 78.70H             |
| ▶ AFS Inlet Barrier Filter / 7100               | Donaldson/                    | 121300-103     | 0523       |              | 4500.00H            | 2671.20H<br>Oct 23, 22 | 531.70H       | 6639.50H               | 618.50H<br>9.27M    | 618.50H  | 3881.50H           |
| ▶ Airbus Airframe Fuel Filter / 2800            | Airbus/<br>SH02-42            | ICA-ECL-118    |            |              |                     |                        |               |                        |                     |          |                    |
| ▶ Airbus Rear Driveshaft End Cap / Ins 6500     | Airbus/<br>SH12-12            | ICA-ECL-250    |            |              |                     |                        |               |                        |                     |          |                    |
| ▶ Battery / On 2400                             | Concorde/                     | RG350          | 41265567   | 47901        |                     | 2679.70H<br>Dec 4, 22  |               |                        | 78.30H<br>7.90M     | 78.30H   |                    |
| ▶ Facet Scavenge Oil Filter / 7900              | Purolator/<br>SH92-36         | 1742510-1      |            |              |                     |                        |               |                        |                     |          |                    |
| ▶ IFS/RSG Air Conditioning System / Ins 2100    | RSG Products/<br>STC SH3509SW | IFSE-007       |            |              |                     |                        |               |                        |                     |          |                    |
| <b>Main Gearbox &amp; Main Rotor Assembly /</b> |                               |                |            |              |                     |                        |               |                        |                     |          |                    |
| ▶ Bevel Reduction Gear / Ove 6320               | Airbus/                       | 350A32-0350-02 | M4133      |              | 3000.00H<br>288.00M | 354.80H<br>Nov 30, 12  | 354.80H       | 3000.00H<br>Nov 30, 36 | 2758.00H<br>128.03M | 2758.00H | 242.00H<br>159.97M |
| ▶ Epicyclic Reduction Gear / Ove 6320           | Airbus/                       | 350A32-0120-00 | M7938      |              | 3000.00H<br>288.00M | 0.00H<br>Feb 1, 09     |               | 3000.00H<br>Feb 1, 33  | 2758.00H<br>174.00M |          | 242.00H<br>114.00M |
| ▶ Front Bar / Ret 6330                          | Airbus/                       | 704A33-633-262 | 2651       |              | 20000.00H           | 0.00H                  |               | 20000.00H              | 2758.00H            |          | 17242.00H          |
| ▶ Front Bar / Ret 6330                          | Airbus/                       | 704A33-633-262 | 2663       |              | 20000.00H           | 0.00H                  |               | 20000.00H              | 2758.00H            |          | 17242.00H          |
| ▶ Main Rotor Blade (Blue) / Ret                 | Airbus/                       | 355A11-0030-04 | 31206      |              | 20000.00H           | 0.00H                  | 0.00H         | 20000.00H              | 2758.00H            | 3209.70H | 17242.00H          |

Components

| Component/Action                             | Make/Model | Part No.       | Serial No. | Tracking No. | Limit             | Perf.                  | Time at Inst. | Due                    | TTSC                | TTSN     | Rem.              |
|--|------------|----------------|------------|--------------|-------------------|------------------------|---------------|------------------------|---------------------|----------|-------------------|
| 6210   |            |                |            |              |                   |                        |               |                        |                     |          |                   |
| ▸ Main Rotor Blade (Red) / Ret<br>6210       | Airbus/    | 355A11-0030-04 | 31236      |              | 20000.00H         | 354.80H                | 352.30H       | 20002.50H              | 2755.50H            | 2852.40H | 17244.50H         |
| ▸ Main Rotor Blade (Yellow) / Ret<br>6210    | Airbus/    | 355A11-0030-04 | 40455      |              | 20000.00H         | 357.80H                | 0.00H         | 20357.80H              | 2400.20H            | 2494.10H | 17599.80H         |
| ▸ Main Rotor Hub / On<br>6220                | Airbus/    | 355A31-0002-01 | M3496      |              |                   | 354.80H<br>Nov 30, 12  | 354.80H       |                        | 2758.00H<br>128.03M | 2758.00H |                   |
| ▸ Main Rotor Mast / On<br>6230               | Airbus/    | 355A37-0006-00 | M999       |              |                   | 451.70H<br>Nov 12, 14  | 451.70H       |                        | 2758.00H<br>104.63M | 3139.30H |                   |
| ▸ Main Servocontrol (Fore/Aft) / Ret<br>6730 | Airbus/    | SC8042         | 2701       |              | 20000.00H         | 2106.80H<br>Nov 24, 19 | 3191.70H      | 18915.10H              | 3842.90H<br>44.23M  | 3842.90H | 16157.10H         |
| ▸ Main Servocontrol (L/H) / Ret<br>6730      | Airbus/    | SC8042         | 3240       |              | 20000.00H         | 2405.40H<br>Mar 31, 22 | 2560.32H      | 19845.08H              | 2912.92H<br>16.00M  | 2912.92H | 17087.08H         |
| ▸ Main Servocontrol (R/H) / Ret<br>6730      | Airbus/    | SC8043         | 1118       |              | 20000.00H         | 0.00H<br>Feb 1, 09     | 0.00H         | 20000.00H              | 2758.00H<br>174.00M | 2758.00H | 17242.00H         |
| ▸ Oil Filter / Ret<br>6320                   | Airbus/    | FA01315A       |            |              | 600.00H<br>24.00M | 2316.70H<br>Jul 28, 21 |               | 2916.70H<br>Jul 28, 23 | 441.30H<br>24.10M   |          | 158.70H<br>-0.10M |
| ▸ Oil Pump / Ove<br>6300                     | Airbus/    | 350A32-0400-00 | M4312      |              | 4000.00H          | 0.00H                  |               | 4000.00H               | 2758.00H            |          | 1242.00H          |
| ▸ Rear Bar / Ret<br>6330                     | Airbus/    | 704A33-633-075 | 9389       |              | 20000.00H         | 0.00H                  |               | 20000.00H              | 2758.00H            |          | 17242.00H         |
| ▸ Rear Bar / Ret<br>6330                     | Airbus/    | 704A33-633-075 | 9394       |              | 20000.00H         | 0.00H                  |               | 20000.00H              | 2758.00H            |          | 17242.00H         |
| ▸ Rotor Brake / On<br>6300                   | Airbus/    | 350A32-0500-02 | LT1320     |              |                   | 0.00H                  |               |                        | 2758.00H            |          |                   |
| Re-weigh / Rew                               | /          |                |            |              |                   | 451.70H                |               |                        | 2306.30H            |          |                   |

**Components**

| Component/Action                                     | Make/Model        | Part No.              | Serial No.  | Tracking No. | Limit               | Perf.                  | Time at Inst. | Due                    | TTSC                | TTSN     | Rem.                |
|--|-------------------|-----------------------|-------------|--------------|---------------------|------------------------|---------------|------------------------|---------------------|----------|---------------------|
| 0810   |                   |                       |             |              | 72.00M*             | Nov 12, 14 *           |               | Feb 1, 24 *            | 104.63M*            | *        | 6.00M*              |
|  |                   |                       |             |              |                     |                        |               |                        |                     |          | EXT                 |
| Starter Generator / Ove<br>8000                      | Airbus/<br>Skurka | 150SG122Q             | 8733        | 41263        | 900.00H<br>60.00M   | 2030.60H<br>Aug 23, 19 | 0.00H         | 2930.60H<br>Aug 23, 24 | 727.40H<br>47.27M   | 2918.60H | 172.60H<br>12.73M   |
| Tail Rotor Drive Shaft<br>Asseby, EC130 / On<br>6500 | Airbus/           | 350A34-0212-00        | PPT00408    |              |                     | 2.30H<br>Jun 1, 09     |               |                        | 2755.70H<br>170.00M | 2755.70H |                     |
| Tail Rotor Gearbox / Ove<br>6520                     | Airbus/           | 350A33-0501-01        | M1417       |              | 4000.00H<br>288.00M | 0.00H<br>Feb 1, 09     |               | 4000.00H<br>Feb 1, 33  | 2758.00H<br>174.00M |          | 1242.00H<br>114.00M |
| <b>Tail Rotor Hub / On<br/>6420</b>                  | <b>Airbus/</b>    | <b>350A33-3100-01</b> | <b>M389</b> |              |                     | <b>0.00H</b>           |               |                        | <b>2758.00H</b>     |          |                     |
| * Tail Rotor Blade Assembly<br>/ Ret<br>6410         | Eurocopter/       | 350A33-3002-02        |             |              |                     |                        |               |                        |                     |          |                     |

" \* " indicates that a Manual Next Due is set.

**Recurring AD's**

| AD No.                                    | Description   | Type  | Limit             | Perf.                  | Due                    | TTSC               | Rem.              |
|---|---|-------|-------------------|------------------------|------------------------|--------------------|-------------------|
| AD 2016-0023<br><br>Cycle Name : Landings | Rotor Drive - Main Gearbox Main and Bottom Casings -<br>Inspection / Replacement.                                       | Recur |                   | 874.00H<br>Jun 24, 16  |                        | 1884.00H<br>85.23M |                   |
|   |   |       | 22800.0C*         | 2506.0C*               | 77100.0C*              | 8785.0C*           | 65809.0C*         |
| AD 2017-0059 (Para 4)                     | Engine Controls - Switches 53Ka, 53Kb and 65K –<br>Insp./Modification (EASB 05.00.61 (R3) (Para 3)).                    | Recur | 600.00H<br>12.00M | 2756.60H<br>Jul 25, 23 | 3356.60H<br>Jul 25, 24 | 1.40H<br>0.20M     | 598.60H<br>11.80M |
| AD 2018-0206, para 1                      | Main Rotor – Mast Upper Bearing Sealant Bead / Inner Race<br>Retaining Rings - Inspection.                              | Recur | 150.00H           | 2670.60H<br>Oct 22, 22 | 2820.60H               | 87.40H<br>9.30M    | 62.60H            |
| AD 2018-0206, para 2                      | Main Rotor – Mast Upper Bearing Sealant Bead / Inner Race<br>Retaining Rings - Inspection.                              | Recur | 600.00H<br>24.00M | 2405.40H<br>Mar 31, 22 | 3005.40H<br>Mar 31, 24 | 352.60H<br>16.00M  | 247.40H<br>8.00M  |
| AD 2020-0069, para 3B1                    | Doors – Sliding Door Opening Mechanism – Inspection (ASB<br>05A031, R1, (para 3.B.1), supersedes AD 2019-0001, para 3). | Recur | 600.00H           | 2756.60H<br>Jul 25, 23 | 3356.60H               | 1.40H<br>0.20M     | 598.60H           |
| AD 2021-09-05, PARA (f)(5)(i)             | TAIL BOOM TO FENESTRON JUNCTION FRAME INSPECTION.   | Recur | 600.00H*          | *                      | 3005.40H*              | *                  | 247.40H*          |

| Recurring AD's                |   |       |                   |                           |                           |                   |                    |
|-------------------------------|---|-------|-------------------|---------------------------|---------------------------|-------------------|--------------------|
| AD No.                        | Description   | Type  | Limit             | Perf.                     | Due                       | TTSC              | Rem.               |
| AD 2022-0150                  | ATA 64 - Tail Rotor - Blades - Inspection.  | Recur | 600.00H*<br>*     | 2683.30H*<br>Dec 12, 22 * | 2907.80H*<br>Mar 31, 24 * | 74.70H*<br>7.63M* | 149.80H*<br>8.00M* |
| AD 2023-0044, Part 1          | PROTECTIVE MEASURE - TIME LIMITS - MAINTENANCE CHECKS - Main rotor drive - Check of the Main Gear Box (MGB) bevel wheel .   | Recur | 660.00H*          | *                         | 3065.40H*                 | *                 | 307.40H*           |
| ASB EC130-05A036              | INDICATING AND RECORDING SYSTEMS - Control unit Inspection of the control panel.  | Recur | 1320.00H          | 2268.90H<br>May 12, 21    | 3588.90H                  | 489.10H<br>26.63M | 830.90H            |
| SB 05-016, Rev 2, Para 3B1 76 | TIME LIMITS - MAINTENANCE CHECKS - Collective pitch control - Periodic check of the drive tube/control pinion bonded connection located on the pilot/copilot twist grips. | Recur | 26.00M            | 2604.70H<br>Sep 5, 22     | Nov 5, 24                 | 153.30H<br>10.87M | 15.13M             |
| SB 05-029, Rev 1              | Hydraulic pump - Greasing of the splines of the secondary hydraulic pump.   | Recur | 300.00H<br>12.00M | 2683.30H<br>Dec 12, 22    | 2983.30H<br>Dec 12, 23    | 74.70H<br>7.63M   | 225.30H<br>4.37M   |

" \* " indicates that a Manual Next Due is set.

| Inspections   |                    |                        |                        |                   |                  |
|---|--------------------|------------------------|------------------------|-------------------|------------------|
| Inspection  | Limit              | Perf.                  | Due                    | TTSC              | Rem.             |
| 100 Hour Airframe Inspection. IAW 04-20-00, 05-21-00/-01/-02, 05-25-00  | 100.00H            | 2746.40H<br>Mar 16, 23 | 2846.40H               | 11.60H<br>4.50M   | 88.40H           |
| 100 Hour Airworthiness Directive verification. Re-inspect all ADs inspected under elementary task authority with less than 100 hr repetitive requirements. Ref CAR STD 625 Appendix A #29 | 100.00H<br>12.00M  | 2705.80H<br>Jan 19, 23 | 2805.80H<br>Jan 19, 24 | 52.20H<br>6.40M   | 47.80H<br>5.60M  |
| 1200 Hour/48 Month IAW 05-23-00/-01/-02   | 1200.00H<br>48.00M | 2106.80H<br>Nov 24, 19 | 3306.80H<br>Nov 24, 23 | 651.20H<br>44.23M | 548.80H<br>3.77M |
| 144 Month Bonding (AMM 24-00-00, 6-2)   | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M    | 143.80M          |
| 144 Month Cabin Floor (AMM 53-00-00, 6-5)   | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M    | 143.80M          |
| 144 Month Engine Parameter Indicators (AMM 77-00-00, 5-1)   | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M    | 143.80M          |



**Inspections**

| Inspection  | Limit              | Perf.                  | Due                    | TTSC            | Rem.               |
|---|--------------------|------------------------|------------------------|-----------------|--------------------|
| 144 Month Engine Support (AMM 71-41-00, 6-1)  | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Fenestron (AMM 53-41-00, 6-2)   | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Fuel Tank (AMM 28-11-00, 6-2)   | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Fuel Tank Compartment (AMM 53-10-00, 6-3)   | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Heating Pipe Check (AMM 21-21-00, 6-2, 6-3)                                       | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month MGB Suspension Bar Fittings (AMM 63-32-00, 6-6)                                   | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Oil Cooler (AMM 79-21-00, 3-1)  | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Rotor Flight Control Channels (AMM 67-00-00, 6-2, 6-4)                            | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Skid Type Landing Gear (AMM 32-11-00, 6-6)  | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 144 Month Tail Boom-to-Fuselage Junction (AMM 53-31-00, 6-8)                                | 144.00M            | 2756.60H<br>Jul 25, 23 | Jul 25, 35             | 1.40H<br>0.20M  | 143.80M            |
| 150 Hour/12 Month - BHP REQUIREMENT - INSPECT SEAT BELTS CUTTERS FOR CONDITION AND SECURITY | 150.00H<br>12.00M  | 2670.60H<br>Oct 22, 22 | 2820.60H<br>Oct 22, 23 | 87.40H<br>9.30M | 62.60H<br>2.70M    |
| 150 Hour/12 Month Airframe Inspection. IAW 04-20-00, 05-21-00/-01/-02, 05-25-00             | 150.00H<br>12.00M  | 2670.60H<br>Oct 22, 22 | 2820.60H<br>Oct 22, 23 | 87.40H<br>9.30M | 62.60H<br>2.70M    |
| 1800 Hour/72 Month - Heating Pipe (AMM 21-21-00, 6-5)                                       | 1800.00H<br>72.00M | 2756.60H<br>Jul 25, 23 | 4556.60H<br>Jul 25, 29 | 1.40H<br>0.20M  | 1798.60H<br>71.80M |

**Inspections**

| Inspection  | Limit             | Perf.                  | Due                    | TTSC              | Rem.             |
|---|-------------------|------------------------|------------------------|-------------------|------------------|
| 600 Hour/24 Month IAW 04-20-00, 05-22-00/-01/-02  | 600.00H<br>24.00M | 2405.40H<br>Mar 31, 22 | 3005.40H<br>Mar 31, 24 | 352.60H<br>16.00M | 247.40H<br>8.00M |
| 72 Month MGB assy - TGB assy (AMM 05-60-00, 6-1)  | 72.00M*           | *                      | Feb 16, 25 *           | *                 | 18.50M*          |
| 72 Month MRH - Main Rotor Mast - TRH - Tail rotor drive assy - Engine/MGB coupling (AMM 05-60-00, 6-1)  | 72.00M*           | *                      | Feb 16, 25 *           | *                 | 18.50M*          |
| General visual inspection for skid wearplate wear (Note: verify skid wearplates are not worn through causing damage to skid tubes).   | 150.00H           | 2670.60H<br>Oct 22, 22 | 2820.60H               | 87.40H<br>9.30M   | 62.60H           |
| In conjunction with the 100 Hour Airframe Inspection all deferred defects must be rectified or re-deferred and an image of the deferred defects page must be sent to admin. | 100.00H<br>12.00M | 2746.40H<br>Mar 16, 23 | 2846.40H<br>Mar 16, 24 | 11.60H<br>4.50M   | 88.40H<br>7.50M  |

" \* " indicates that a Manual Next Due is set.

**AFS Inlet Barrier Filter - Assembly - PN: 121300-103 SN: 0523**

| Component/Action                                | Make/Model   | Part No.   | Serial No. | Tracking No. | Limit             | Perf.                  | Time at Inst. | Due                    | TTSC              | TTSN    | Rem.             |
|---|--|------------|------------|--------------|-------------------|------------------------|---------------|------------------------|-------------------|---------|------------------|
| AFS Inlet Barrier Filter / 7100                 | Donaldson/   | 121300-103 | 0523       |              | 4500.00H          | 2671.20H<br>Oct 23, 22 | 531.70H       | 6639.50H               | 618.50H<br>9.27M  | 618.50H | 3881.50H         |
| -- 12 Month AFS filter / Ins 7160               | AFS/<br>Carry out an annual inspection as per table 1      | 121300-103 | 0523       |              | 12.00M            | 2623.10H<br>Sep 16, 22 |               | Sep 16, 23             | 134.90H<br>10.50M |         | 1.50M            |
| -- 150 hr AFS filter / Ins 7160                 | AFS/<br>Carry out a 100 Inspection as per ICA table 1      | 121300-103 | 0523       |              | 150.00H           | 2671.20H<br>Oct 23, 22 |               | 2821.20H               | 86.80H<br>9.27M   |         | 63.20H           |
| -- 300 hr / 12 Month Filter cleaning / Cle 7160 | AFS/<br>** scratch mark on filter to identify # of cleanin | 121300-103 | 0523       |              | 300.00H<br>12.00M | 2671.20H<br>Oct 23, 22 |               | 2971.20H<br>Oct 23, 23 | 86.80H<br>9.27M   |         | 213.20H<br>2.73M |

" \* " indicates that a Manual Next Due is set.

**Airbus Airframe Fuel Filter - Assembly - PN: ICA-ECL-118**

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|------------------|------------|----------|------------|--------------|-------|-------|---------------|-----|------|------|------|
|------------------|------------|----------|------------|--------------|-------|-------|---------------|-----|------|------|------|

| Airbus Airframe Fuel Filter - Assembly - PN: ICA-ECL-118  |                     |             |            |              |                   |                        |               |                        |                 |      |                   |
|---|---------------------|-------------|------------|--------------|-------------------|------------------------|---------------|------------------------|-----------------|------|-------------------|
| Component/Action  | Make/Model          | Part No.    | Serial No. | Tracking No. | Limit             | Perf.                  | Time at Inst. | Due                    | TTSC            | TTSN | Rem.              |
| Airbus Airframe Fuel Filter / 2800  | Airbus/ SH02-42     | ICA-ECL-118 |            |              |                   |                        |               |                        |                 |      |                   |
| -- 150 hr / 12 Month Airbus Airframe Fuel Filter Inspection / Ins 2800                                | Airbus/ STC SH02-42 | 1743645-02  |            |              | 150.00H<br>12.00M | 2670.60H<br>Oct 22, 22 |               | 2820.60H<br>Oct 22, 23 | 87.40H<br>9.30M |      | 62.60H<br>2.70M   |
| -- 600 hr / 24 Month Airbus Airframe Fuel Filter Bypass Check & Filter Element Replacement / Ins 2800 | Airbus/ STC SH02-42 | 1743645-02  |            |              | 600.00H<br>24.00M | 2711.60H<br>Jan 26, 23 |               | 3311.60H<br>Jan 26, 25 | 46.40H<br>6.17M |      | 553.60H<br>17.83M |

" \* " indicates that a Manual Next Due is set.

| Airbus Rear Driveshaft End Cap - Assembly - PN: ICA-ECL-250 SN: |                     |             |            |              |                   |                        |               |                        |                   |      |                  |
|---|---------------------|-------------|------------|--------------|-------------------|------------------------|---------------|------------------------|-------------------|------|------------------|
| Component/Action  | Make/Model          | Part No.    | Serial No. | Tracking No. | Limit             | Perf.                  | Time at Inst. | Due                    | TTSC              | TTSN | Rem.             |
| Airbus Rear Driveshaft End Cap / Ins 6500                       | Airbus/ SH12-12     | ICA-ECL-250 |            |              |                   |                        |               |                        |                   |      |                  |
| -- 150 hr / 12 Month Airbus Rear Driveshaft End Cap / Ins 6500  | Airbus/ STC SH12-12 | ICA-ECL-250 |            |              | 150.00H<br>12.00M | 2670.60H<br>Oct 22, 22 |               | 2820.60H<br>Oct 22, 23 | 87.40H<br>9.30M   |      | 62.60H<br>2.70M  |
| -- 600 hr / 24 Month Airbus Rear Driveshaft End Cap / Ins 6500  | Airbus/ STC SH12-12 | ICA-ECL-250 |            |              | 600.00H<br>24.00M | 2405.40H<br>Mar 31, 22 |               | 3005.40H<br>Mar 31, 24 | 352.60H<br>16.00M |      | 247.40H<br>8.00M |

" \* " indicates that a Manual Next Due is set.

| Bevel Reduction Gear - Assembly - PN: 350A32-0350-02 SN: M4133 |            |                |            |              |                     |                       |               |                        |                     |          |                    |
|--|------------|----------------|------------|--------------|---------------------|-----------------------|---------------|------------------------|---------------------|----------|--------------------|
| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit               | Perf.                 | Time at Inst. | Due                    | TTSC                | TTSN     | Rem.               |
| Bevel Reduction Gear / Ove 6320                                | Airbus/    | 350A32-0350-02 | M4133      |              | 3000.00H<br>288.00M | 354.80H<br>Nov 30, 12 | 354.80H       | 3000.00H<br>Nov 30, 36 | 2758.00H<br>128.03M | 2758.00H | 242.00H<br>159.97M |
| -- Bevel Wheel / Ret 6320                                      | Airbus/    | 350A32-3166-20 | L2220      |              | 20000.00H           | 0.00H                 |               | 20000.00H              | 2758.00H            |          | 17242.00H          |
| -- Input Bevel Pinion / Ret 6320                               | Airbus/    | 350A32-3172-20 | M976       |              | 20000.00H           | 0.00H                 |               | 20000.00H              | 2758.00H            |          | 17242.00H          |
| -- Lower Housing Equipped / Ret 6321                           | Airbus/    | 350A32-3119-06 |            |              |                     | 0.00H<br>Oct 10, 08   |               |                        | 2758.00H<br>177.70M | 2758.00H |                    |

| Bevel Reduction Gear - Assembly - PN: 350A32-0350-02 SN: M4133  |            |                |            |              |                         |                        |               |                         |                       |      |                         |
|---|------------|----------------|------------|--------------|-------------------------|------------------------|---------------|-------------------------|-----------------------|------|-------------------------|
| Component/Action  | Make/Model | Part No.       | Serial No. | Tracking No. | Limit                   | Perf.                  | Time at Inst. | Due                     | TTSC                  | TTSN | Rem.                    |
| Cycle Name : Landings   |            |                |            |              | 77900.00C               | 0.00C                  |               | 77900.00C               | 11291.00C             |      | 66609.00C               |
| -- Main Housing Assembly / Ret<br>6320<br>Cycle Name : Landings | Airbus/    | 350A32-3156-21 | MAP456     |              | 20000.00H<br>120000.00C | 0.00H<br>0.00C         |               | 20000.00H<br>120000.00C | 2758.00H<br>11291.00C |      | 17242.00H<br>108709.00C |
| -- MGB Bottom Casing / Ret<br>6320<br>Cycle Name : Landings     | Airbus/    | 350A32-3119-05 | MAP7718    |              | 20000.00H<br>120000.00C | 0.00H<br>0.00C         |               | 20000.00H<br>120000.00C | 2758.00H<br>11291.00C |      | 17242.00H<br>108709.00C |
| -- MGB Oil Change / Lub<br>6320                                 | Airbus/    |                |            |              | 500.00H<br>24.00M       | 2591.90H<br>Aug 29, 22 |               | 3091.90H<br>Aug 29, 24  | 166.10H<br>11.07M     |      | 333.90H<br>12.93M       |

" \* " indicates that a Manual Next Due is set.

| Cabin Fire Extinguisher - Assembly - PN: C352 SN: X-983720 |             |          |            |              |         |                        |               |            |                |      |        |
|--|-------------|----------|------------|--------------|---------|------------------------|---------------|------------|----------------|------|--------|
| Component/Action   | Make/Model  | Part No. | Serial No. | Tracking No. | Limit   | Perf.                  | Time at Inst. | Due        | TTSC           | TTSN | Rem.   |
| Cabin Fire Extinguisher / Hyd<br>2560                      | Amerex/     | C352     | X-983720   |              | 144.00M | Nov 12, 14             |               | Nov 12, 26 | 104.63M        |      | 39.37M |
| -- 12 Month Cabin Fire Extinguisher /<br>Ins<br>2560       | CAR 625/    | C352     | X-983720   |              | 12.00M  | 2756.60H<br>Jul 25, 23 |               | Jul 25, 24 | 1.40H<br>0.20M |      | 11.80M |
| -- 6 Month Cabin Fire Extinguisher /<br>Che<br>2560        | Eurocopter/ | C352     | X-983720   |              | 6.00M   | 2756.60H<br>Jul 25, 23 |               | Jan 25, 24 | 1.40H<br>0.20M |      | 5.80M  |

" \* " indicates that a Manual Next Due is set.

| ELT - Assembly - PN: S1822502-02 SN: 2621038-0045 |                            |             |              |              |        |                          |                 |              |                  |      |         |
|---|----------------------------|-------------|--------------|--------------|--------|--------------------------|-----------------|--------------|------------------|------|---------|
| Component/Action                                  | Make/Model                 | Part No.    | Serial No.   | Tracking No. | Limit  | Perf.                    | Time at Inst.   | Due          | TTSC             | TTSN | Rem.    |
| ELT / Ins<br>2560                                 | /                          | S1822502-02 | 2621038-0045 | 34639        | *      | 2718.90H<br>Jan 30, 23 * | 0.00H<br>0.00 * | Jan 24, 25 * | 39.10H<br>6.03M* | *    | 17.77M* |
| -- 1 Month ELT / Tes<br>2560                      | Kannad/<br>Kannad 406 AF-H | S1822502-02 |              |              | 1.00M  | 2733.40H<br>Mar 2, 23    |                 | Apr 2, 23    | 24.60H<br>4.97M  |      | -3.97M  |
| -- 24 Month ELT / Re-<br>2560                     | Kannad/<br>Kannad 406 AF-H | S1822502-02 |              |              | 24.00M | 2718.90H<br>Jan 30, 23   |                 | Jan 30, 25   | 39.10H<br>6.03M  |      | 17.97M  |

| ELT - Assembly - PN: S1822502-02 SN: 2621038-0045 |            |          |            |              |        |                        |               |            |                 |      |        |
|---|------------|----------|------------|--------------|--------|------------------------|---------------|------------|-----------------|------|--------|
| Component/Action                                  | Make/Model | Part No. | Serial No. | Tracking No. | Limit  | Perf.                  | Time at Inst. | Due        | TTSC            | TTSN | Rem.   |
| -- 72 Month ELT Battery / Rep<br>2560             | Kannad/    |          |            |              | 72.00M | 2718.90H<br>Jan 30, 23 |               | Jan 30, 29 | 39.10H<br>6.03M |      | 65.97M |

" \* " indicates that a Manual Next Due is set.

| Engine - Assembly - PN: 0292005410 SN: 46245   |                          |            |            |              |                     |                        |               |                        |                     |          |                  |
|--|--------------------------|------------|------------|--------------|---------------------|------------------------|---------------|------------------------|---------------------|----------|------------------|
| Component/Action   | Make/Model               | Part No.   | Serial No. | Tracking No. | Limit               | Perf.                  | Time at Inst. | Due                    | TTSC                | TTSN     | Rem.             |
| Engine / Ove<br>7200   | Safran/<br>Arriel 2B1    | 0292005410 | 46245      |              | 3500.00H<br>180.00M | 0.00H<br>Feb 1, 09     |               | 3500.00H<br>Feb 1, 24  | 2758.00H<br>174.00M | 2758.00H | 742.00H<br>6.00M |
| -- 150 hr Engine (05-20-10-201-825-<br>A01) / Ins<br>7200  | Safran/<br>Arriel 2B1    |            |            |              | 150.00H             | 2670.20H<br>Oct 18, 22 |               | 2820.20H               | 87.80H<br>9.43M     |          | 62.20H           |
| -- 25 Hour Engine Power Check ***This<br>is an AIRWORTHINESS LIMITATION<br>on the Arriel 2B1 Engine*** / Che<br>7200 | /                        |            |            |              | 25.00H              | 2757.60H<br>Jul 31, 23 |               | 2782.60H               | 0.40H<br>0.00M      |          | 24.60H           |
| -- 300 hr Ignition plugs REF 72-43-00-<br>200-803, 72-43-00-200-806-A02; BHL P<br>requirement; / Ins<br>7200         | Turbomeca/<br>Arriel 2B1 |            |            |              | 300.00H             | 2536.70H<br>Aug 4, 22  |               | 2836.70H               | 221.30H<br>11.90M   |          | 78.70H           |
| -- 300 hr Engine (05-20-10-201-835-<br>A01) / Ins<br>7200  | Turbomeca/<br>Arriel 2B1 |            |            |              | 300.00H             | 2536.70H<br>Aug 3, 22  |               | 2836.70H               | 221.30H<br>11.93M   |          | 78.70H           |
| -- 600 hr / 24 Month Engine 05-20-10-<br>201-850-A01 / Ins<br>7200   | Turbomeca/<br>Arriel 2B1 |            |            |              | 600.00H<br>24.00M   | 2405.40H<br>Mar 31, 22 |               | 3005.40H<br>Mar 31, 24 | 352.60H<br>16.00M   |          | 247.40H<br>8.00M |

" \* " indicates that a Manual Next Due is set.

| Epicyclic Reduction Gear - Assembly - PN: 350A32-0120-00 SN: M7938 |            |                |            |              |                     |                    |               |                       |                     |      |                    |
|--|------------|----------------|------------|--------------|---------------------|--------------------|---------------|-----------------------|---------------------|------|--------------------|
| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit               | Perf.              | Time at Inst. | Due                   | TTSC                | TTSN | Rem.               |
| Epicyclic Reduction Gear / Ove<br>6320                             | Airbus/    | 350A32-0120-00 | M7938      |              | 3000.00H<br>288.00M | 0.00H<br>Feb 1, 09 |               | 3000.00H<br>Feb 1, 33 | 2758.00H<br>174.00M |      | 242.00H<br>114.00M |
| -- Fixed Ring Gear / Ret<br>6320                                   | Airbus/    | 350A32-1086-23 | M1445      |              | 20000.00H           | 0.00H              |               | 20000.00H             | 2758.00H            |      | 17242.00H          |
| -- Planet Gear Cage / Ret<br>6320                                  | Airbus/    | 350A32-1089-21 | CUR01461   |              |                     |                    |               |                       |                     |      |                    |

| Epicyclic Reduction Gear - Assembly - PN: 350A32-0120-00 SN: M7938 |            |                |            |              |           |       |               |           |           |      |           |
|--|------------|----------------|------------|--------------|-----------|-------|---------------|-----------|-----------|------|-----------|
| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit     | Perf. | Time at Inst. | Due       | TTSC      | TTSN | Rem.      |
| Cycle Name : Landings  |            |                |            |              | 49000.00C | 0.00C |               | 49000.00C | 11291.00C |      | 37709.00C |
| -- Planet Gear, Unequipped (#1) / Ret 6320                         | Airbus/    | 350A32-1082-20 | M4954      |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H  |      | 17242.00H |
| -- Planet Gear, Unequipped (#2) / Ret 6320                         | Airbus/    | 350A32-1082-20 | M4964      |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H  |      | 17242.00H |
| -- Planet Gear, Unequipped (#5) / Ret 6320                         | Airbus/    | 350A32-1082-20 | M5167      |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H  |      | 17242.00H |
| -- Planet Gear, Unequipped (#3) / Ret 6320                         | Airbus/    | 350A32-1082-20 | M5117      |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H  |      | 17242.00H |
| -- Planet Gear, Unequipped (#4) / Ret 6320                         | Airbus/    | 350A32-1082-20 | M5144      |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H  |      | 17242.00H |
| -- Sun Gear / Ret 6320   | Airbus/    | 350A32-1075-20 | M304       |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H  |      | 17242.00H |

" \* " indicates that a Manual Next Due is set.

| Facet Scavenge Oil Filter - Assembly - PN: 1742510-1              |                        |           |            |              |                   |                        |               |                        |                   |      |                   |
|---|------------------------|-----------|------------|--------------|-------------------|------------------------|---------------|------------------------|-------------------|------|-------------------|
| Component/Action  | Make/Model             | Part No.  | Serial No. | Tracking No. | Limit             | Perf.                  | Time at Inst. | Due                    | TTSC              | TTSN | Rem.              |
| Facet Scavenge Oil Filter / 7900                                  | Purolator/ SH92-36     | 1742510-1 |            |              |                   |                        |               |                        |                   |      |                   |
| -- 750 hr / 12 Month Facet Scavenge Oil Filter Element / Rep 7900 | Purolator/ STC SH92-36 | 1742510-1 |            |              | 750.00H<br>12.00M | 2756.60H<br>Jul 25, 23 |               | 3506.60H<br>Jul 25, 24 | 1.40H<br>0.20M    |      | 748.60H<br>11.80M |
| -- 800 hr Facet Scavenge Oil Filter Bypass Check / Che 7900       | Purolator/ STC SH92-36 | 1742510-1 |            |              | 800.00H           | 2405.40H<br>Mar 31, 22 |               | 3205.40H               | 352.60H<br>16.00M |      | 447.40H           |

" \* " indicates that a Manual Next Due is set.

| Freewheel Shaft Assembly - Assembly - PN: 0292900020 |            |          |            |              |       |       |               |     |      |      |      |
|--|------------|----------|------------|--------------|-------|-------|---------------|-----|------|------|------|
| Component/Action                                     | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |

| Freewheel Shaft Assembly - Assembly - PN: 0292900020   |                  |                               |            |              |                        |                              |               |                        |                                  |                       |                       |  |
|--|------------------|-------------------------------|------------|--------------|------------------------|------------------------------|---------------|------------------------|----------------------------------|-----------------------|-----------------------|--|
| Component/Action                                       | Make/Model       | Part No.                      | Serial No. | Tracking No. | Limit                  | Perf.                        | Time at Inst. | Due                    | TTSC                             | TTSN                  | Rem.                  |  |
| Freewheel Shaft Assembly / Ove 7200                    | Safran/ Arriel 2 | 0292900020                    |            |              |                        | 0.00H<br>Oct 10, 08          |               |                        | 2758.00H<br>177.70M              | 2758.00H              |                       |  |
| -- Bearing / Ret 7200                                  | Safran/ Arriel 2 | 9608650992                    | 79         |              | 7000.00H               | 0.00H<br>Oct 10, 08          |               | 7000.00H               | 2758.00H<br>177.70M              | 2758.00H              | 4242.00H              |  |
| -- Freewheel / Ret 7200                                | Safran/ Arriel 2 | 9292900010                    | 138        |              | 3500.00H<br>180.00M    | 0.00H<br>Oct 10, 08          |               | 3500.00H<br>Oct 10, 23 | 2758.00H<br>177.70M              | 2758.00H<br>177.70M   | 742.00H<br>2.30M      |  |
| -- Freewheel Shaft / Ret 7200<br>Cycle Name : Landings | Safran/ Arriel 2 | 0292900030                    | 1183       |              | 12000.00H<br>72000.00C | 0.00H<br>Oct 10, 08<br>0.00C |               | 12000.00H<br>72000.00C | 2758.00H<br>177.70M<br>11291.00C | 2758.00H<br>11291.00C | 9242.00H<br>60709.00C |  |
| -- Splined Sleeve / Ret 6321<br>Cycle Name : Landings  |                  | 350A35-1210-20/0.292.90.016.0 |            |              |                        | 0.00H<br>Oct 10, 08<br>0.00C |               |                        | 2758.00H<br>177.70M<br>11291.00C | 2758.00H              | 60709.00C             |  |

" \* " indicates that a Manual Next Due is set.

| IFS/RSG Air Conditioning System - Assembly - PN: IFSE-007 SN: |                            |          |            |              |                   |                        |               |                        |                 |      |                 |  |
|---|----------------------------|----------|------------|--------------|-------------------|------------------------|---------------|------------------------|-----------------|------|-----------------|--|
| Component/Action  | Make/Model                 | Part No. | Serial No. | Tracking No. | Limit             | Perf.                  | Time at Inst. | Due                    | TTSC            | TTSN | Rem.            |  |
| IFS/RSG Air Conditioning System / Ins 2100                    | RSG Products/ STC SH3509SW | IFSE-007 |            |              |                   |                        |               |                        |                 |      |                 |  |
| -- 150 hr / 12 Month Air Conditioning / Ins 2500              | RSG Products/ STC SH3509SW | IFSE-007 |            |              | 150.00H<br>12.00M | 2670.60H<br>Oct 22, 22 |               | 2820.60H<br>Oct 22, 23 | 87.40H<br>9.30M |      | 62.60H<br>2.70M |  |

" \* " indicates that a Manual Next Due is set.

| M02 - Axial Compressor - Assembly - PN: 70BM022010 SN: 7624    |                     |            |            |              |           |                    |               |           |                     |      |           |  |
|--|---------------------|------------|------------|--------------|-----------|--------------------|---------------|-----------|---------------------|------|-----------|--|
| Component/Action   | Make/Model          | Part No.   | Serial No. | Tracking No. | Limit     | Perf.              | Time at Inst. | Due       | TTSC                | TTSN | Rem.      |  |
| M02 - Axial Compressor / Ove 7200                              | Safran/ Arriel 2    | 70BM022010 | 7624       |              | 3500.00H  | 0.00H<br>Nov 1, 08 |               | 3500.00H  | 2758.00H<br>177.00M |      | 742.00H   |  |
| -- Axial Compressor Wheel / Ret 7200<br>Cycle Name : NG CYCLES | Turbomeca/ Arriel 2 | 2292153270 | 5928FB     |              | 22000.00C | 0.00C              |               | 22000.00C | 7172.90C            |      | 14827.10C |  |
| -- Bearing (#1) / Ret 7200                                     | Turbomeca/ Arriel 2 | 9609000486 | 5472       |              | 7000.00H  | 0.00H              |               | 7000.00H  | 2758.00H            |      | 4242.00H  |  |

| M02 - Axial Compressor - Assembly - PN: 70BM022010 SN: 7624 |                        |            |            |              |          |       |               |          |          |      |          |
|---|------------------------|------------|------------|--------------|----------|-------|---------------|----------|----------|------|----------|
| Component/Action  | Make/Model             | Part No.   | Serial No. | Tracking No. | Limit    | Perf. | Time at Inst. | Due      | TTSC     | TTSN | Rem.     |
| Cycle Name : NG CYCLES                                      |                        |            |            |              |          | 0.00C |               |          | 7172.90C |      |          |
| -- Bearing (#2) / Ret<br>7200<br>Cycle Name : NG CYCLES     | Turbomeca/<br>Arriel 2 | 9609000486 | 5482       |              | 7000.00H | 0.00H |               | 7000.00H | 2758.00H |      | 4242.00H |
|   |                        |            |            |              |          | 0.00C |               |          | 7172.90C |      |          |
| -- Bearing / Ret<br>7200                                    | Turbomeca/<br>Arriel 2 | 9606490202 | 17908      |              | 7000.00H | 0.00H |               | 7000.00H | 2758.00H |      | 4242.00H |

" \* " indicates that a Manual Next Due is set.

| M03 - Gas Generator - Assembly - PN: 70BM032030 SN: 9824        |                        |            |            |              |                       |                                    |                    |                       |                               |                     |                      |
|---|------------------------|------------|------------|--------------|-----------------------|------------------------------------|--------------------|-----------------------|-------------------------------|---------------------|----------------------|
| Component/Action  | Make/Model             | Part No.   | Serial No. | Tracking No. | Limit                 | Perf.                              | Time at Inst.      | Due                   | TTSC                          | TTSN                | Rem.                 |
| M03 - Gas Generator / Ove<br>7200                               | Safran/                | 70BM032030 | 9824       | 44537        | 3500.00H<br>180.00M   | 2405.40H<br>Mar 31, 22             | 2405.40H<br>155.70 | 3500.00H<br>Apr 9, 24 | 2758.00H<br>171.70M           | 2758.00H            | 742.00H<br>8.27M     |
| -- Bearing / Ret<br>7200  | Turbomeca/<br>Arriel 2 | 9609000493 | 3018       |              | 7000.00H              | 0.00H                              |                    | 7000.00H              | 2758.00H                      |                     | 4242.00H             |
| -- Centrifugal Impeller / Ret<br>7200<br>Cycle Name : NG CYCLES | Turbomeca/<br>Arriel 2 | 0292260880 | 1480CAR    |              | 22000.00C             | 0.00C                              |                    | 22000.00C             | 7172.90C                      |                     | 14827.10C            |
| -- HP Turbine Blades / Ret<br>7200<br>Cycle Name : NG CYCLES    | Turbomeca/<br>Arriel 2 | 229226A0B0 | BN9        |              | 6000.00H<br>10000.00C | 0.00H<br>0.00C                     |                    | 6000.00H<br>10000.00C | 2758.00H<br>7172.90C          |                     | 3242.00H<br>2827.10C |
| -- HP Turbine Disc / Ret<br>7200<br>Cycle Name : NG CYCLES      | Turbomeca/<br>Arriel 2 | 2292260060 | 10635UP    |              | 17000.00C             | 0.00C                              |                    | 17000.00C             | 7172.90C                      |                     | 9827.10C             |
| -- Injection Wheel / Ret<br>7200<br>Cycle Name : NG CYCLES      | Turbomeca/<br>Arriel 2 | 2292260870 | EE951CTF   |              | 6500.00C              | 2405.40H<br>Mar 31, 22<br>6167.65C |                    | 12667.65C             | 352.60H<br>16.00M<br>1005.25C | 352.60H<br>1005.25C | 5494.75C             |

" \* " indicates that a Manual Next Due is set.

| M04 - Free Turbine - Assembly - PN: 70BM041720 SN: 6581 |                     |            |            |              |          |                    |               |          |                     |      |         |
|---|---------------------|------------|------------|--------------|----------|--------------------|---------------|----------|---------------------|------|---------|
| Component/Action  | Make/Model          | Part No.   | Serial No. | Tracking No. | Limit    | Perf.              | Time at Inst. | Due      | TTSC                | TTSN | Rem.    |
| M04 - Free Turbine / Ove<br>7200                        | Safran/<br>Arriel 2 | 70BM041720 | 6581       |              | 3500.00H | 0.00H<br>Nov 1, 08 |               | 3500.00H | 2758.00H<br>177.00M |      | 742.00H |



| M04 - Free Turbine - Assembly - PN: 70BM041720 SN: 6581             |                        |            |            |              |                       |                |               |                       |                      |      |                      |
|---|------------------------|------------|------------|--------------|-----------------------|----------------|---------------|-----------------------|----------------------|------|----------------------|
| Component/Action  | Make/Model             | Part No.   | Serial No. | Tracking No. | Limit                 | Perf.          | Time at Inst. | Due                   | TTSC                 | TTSN | Rem.                 |
| -- Bearing / Ret<br>7200  | Turbomeca/<br>Arriel 2 | 9609000554 | 2939       |              | 3500.00H              | 0.00H          |               | 3500.00H              | 2758.00H             |      | 742.00H              |
| -- Bearing / Ret<br>7200  | Turbomeca/<br>Arriel 2 | 9609000166 | 15267      |              | 3500.00H              | 0.00H          |               | 3500.00H              | 2758.00H             |      | 742.00H              |
| -- Free Turbine Blades / Ret<br>7200<br>Cycle Name : NP / NF CYCLES | Turbomeca/<br>Arriel 2 | 229281A010 | LX3        |              | 6000.00H<br>10000.00C | 0.00H<br>0.00C |               | 6000.00H<br>10000.00C | 2758.00H<br>3855.50C |      | 3242.00H<br>6144.50C |
| -- Free Turbine Disc / Ret<br>7200<br>Cycle Name : NP / NF CYCLES   | Turbomeca/<br>Arriel 2 | 2292810790 | APL1272TY  |              | 22000.00C             | 0.00C          |               | 22000.00C             | 3855.50C             |      | 18144.50C            |
| -- Free Turbine Nut / Ret<br>7200                                   | Turbomeca/<br>Arriel 2 | 0292810450 | 2312       |              | 3500.00H              | 0.00H          |               | 3500.00H              | 2758.00H             |      | 742.00H              |

" \* " indicates that a Manual Next Due is set.

| M05 - Reduction Gearbox - Assembly - PN: 70BM052000 SN: 10518 |                        |            |            |              |          |                    |               |          |                     |      |          |
|---|------------------------|------------|------------|--------------|----------|--------------------|---------------|----------|---------------------|------|----------|
| Component/Action  | Make/Model             | Part No.   | Serial No. | Tracking No. | Limit    | Perf.              | Time at Inst. | Due      | TTSC                | TTSN | Rem.     |
| M05 - Reduction Gearbox / Ove<br>7200                         | Safran/<br>Arriel 2    | 70BM052000 | 10518      |              | 3500.00H | 0.00H<br>Nov 1, 08 |               | 3500.00H | 2758.00H<br>177.00M |      | 742.00H  |
| -- Bearing (#1) / Ret<br>7200                                 | Turbomeca/<br>Arriel 2 | 9609000619 | 4471       |              | 7000.00H | 0.00H              |               | 7000.00H | 2758.00H            |      | 4242.00H |
| -- Bearing (#2) / Ret<br>7200                                 | Turbomeca/<br>Arriel 2 | 9609000619 | 4476       |              | 7000.00H | 0.00H              |               | 7000.00H | 2758.00H            |      | 4242.00H |
| -- Bearing / Ret<br>7200                                      | Turbomeca/<br>Arriel 2 | 9609000489 | 3305       |              | 7000.00H | 0.00H              |               | 7000.00H | 2758.00H            |      | 4242.00H |
| -- Bearing / Ret<br>7200                                      | Turbomeca/<br>Arriel 2 | 9609000514 | 2997       |              | 7000.00H | 0.00H              |               | 7000.00H | 2758.00H            |      | 4242.00H |
| -- Bearing (#1) / Ret<br>7200                                 | Turbomeca/<br>Arriel 2 | 9609000676 | 2678       |              | 3500.00H | 0.00H              |               | 3500.00H | 2758.00H            |      | 742.00H  |

| M05 - Reduction Gearbox - Assembly - PN: 70BM052000 SN: 10518 |                        |            |            |              |          |       |               |          |          |      |          |
|---|------------------------|------------|------------|--------------|----------|-------|---------------|----------|----------|------|----------|
| Component/Action  | Make/Model             | Part No.   | Serial No. | Tracking No. | Limit    | Perf. | Time at Inst. | Due      | TTSC     | TTSN | Rem.     |
| -- Bearing (#2) / Ret<br>7200                                 | Turbomeca/<br>Arriel 2 | 9609000676 | 2680       |              | 3500.00H | 0.00H |               | 3500.00H | 2758.00H |      | 742.00H  |
| -- Bearing / Ret<br>7200                                      | Turbomeca/<br>Arriel 2 | 9609000585 | 2195       |              | 7000.00H | 0.00H |               | 7000.00H | 2758.00H |      | 4242.00H |
| -- Equipped Sleeve (Coupling Sleeve) /<br>Ret<br>7200         | Turbomeca/<br>Arriel 2 | 0292717600 | 2156TMA    |              | 3500.00H | 0.00H |               | 3500.00H | 2758.00H |      | 742.00H  |
| -- Nut / Ret<br>7200  | Turbomeca/<br>Arriel 2 | 0292710510 | 3729       |              | 3500.00H | 0.00H |               | 3500.00H | 2758.00H |      | 742.00H  |

" \* " indicates that a Manual Next Due is set.

| Main Rotor Hub - Assembly - PN: 355A31-0002-01 SN: M3496 |            |                |            |              |           |                       |               |           |                     |          |           |
|--|------------|----------------|------------|--------------|-----------|-----------------------|---------------|-----------|---------------------|----------|-----------|
| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit     | Perf.                 | Time at Inst. | Due       | TTSC                | TTSN     | Rem.      |
| Main Rotor Hub / On<br>6220                              | Airbus/    | 355A31-0002-01 | M3496      |              |           | 354.80H<br>Nov 30, 12 | 354.80H       |           | 2758.00H<br>128.03M | 2758.00H |           |
| -- Blade Horn (#3) / Ret<br>6220                         | Airbus/    | 350A31-1877-03 | MAP5766    |              | 20000.00H | 0.00H                 |               | 20000.00H | 2758.00H            |          | 17242.00H |
| -- Blade Horn (#1) / Ret<br>6220                         | Airbus/    | 350A31-1877-03 | MAP5628    |              | 20000.00H | 0.00H                 |               | 20000.00H | 2758.00H            |          | 17242.00H |
| -- Blade Horn (#2) / Ret<br>6220                         | Airbus/    | 350A31-1877-03 | MAP5629    |              | 20000.00H | 0.00H                 |               | 20000.00H | 2758.00H            |          | 17242.00H |
| -- Frequency Adapter (#1) / On<br>6220                   | Airbus/    | 704A33-6401-00 | 00871      |              |           | 0.00H                 |               |           | 2758.00H            |          |           |
| -- Frequency Adaptor (#2) / On<br>6220                   | Airbus/    | 704A33-6401-00 | 00876      |              |           | 0.00H                 |               |           | 2758.00H            |          |           |
| -- Frequency Adaptor (#3) / On<br>6220                   | Airbus/    | 704A33-6401-00 | 00880      |              |           | 0.00H                 |               |           | 2758.00H            |          |           |

| Main Rotor Hub - Assembly - PN: 355A31-0002-01 SN: M3496 |            |                  |            |              |          |                        |               |          |                   |         |          |
|--|------------|------------------|------------|--------------|----------|------------------------|---------------|----------|-------------------|---------|----------|
| Component/Action   | Make/Model | Part No.         | Serial No. | Tracking No. | Limit    | Perf.                  | Time at Inst. | Due      | TTSC              | TTSN    | Rem.     |
| -- Lower Sleeve Flange (#1) / Ret<br>6220                | Airbus/    | 350A31-1850-02   | M22536     |              | 6600.00H | 0.00H                  |               | 6600.00H | 2758.00H          |         | 3842.00H |
| -- Lower Sleeve Flange (#2) / Ret<br>6220                | Airbus/    | 350A31-1850-02   | M22537     |              | 6600.00H | 0.00H                  |               | 6600.00H | 2758.00H          |         | 3842.00H |
| -- Lower Sleeve Flange (#3) / Ret<br>6220                | Airbus/    | 350A31-1850-02   | M23091     |              | 6600.00H | 0.00H                  |               | 6600.00H | 2758.00H          |         | 3842.00H |
| -- Spherical Thrust Bearing (#1) / Ret<br>6220           | Airbus/    | 704A33-633-211   | 12219      |              | 4600.00H | 0.00H                  |               | 4600.00H | 2758.00H          |         | 1842.00H |
| -- Spherical Thrust Bearing (#3) / Ret<br>6220           | Airbus/    | 704A33-633-211   | 12221      |              | 4600.00H | 0.00H                  |               | 4600.00H | 2758.00H          |         | 1842.00H |
| -- Spherical Thrust Bearing (#2) / Ret<br>6220           | Airbus/    | 704A33-633-211   | 12220      |              | 4600.00H | 0.00H                  |               | 4600.00H | 2758.00H          |         | 1842.00H |
| -- Spherical Thrust Bearing Bolt (#1)<br>/ Ret<br>6220   | Airbus/    | 350A31-1854-21   | 37832      |              | 3000.00H | 0.00H                  |               | 3000.00H | 2758.00H          |         | 242.00H  |
| -- Spherical Thrust Bearing Bolt (#2)<br>/ Ret<br>6220   | Airbus/    | 350A31-1854-21   | 37839      |              | 3000.00H | 0.00H                  |               | 3000.00H | 2758.00H          |         | 242.00H  |
| -- Spherical Thrust Bearing Bolt (#3)<br>/ Ret<br>6220   | Airbus/    | 350A31-1854-21   | 37844      |              | 3000.00H | 0.00H                  |               | 3000.00H | 2758.00H          |         | 242.00H  |
| -- Spherical Thrust Bearing Bolt (#5)<br>/ Ret<br>6220   | Airbus/    | 350A31-1854-21   | 37876      |              | 3000.00H | 0.00H                  |               | 3000.00H | 2758.00H          |         | 242.00H  |
| -- Spherical Thrust Bearing Bolt (#6)<br>/ Ret<br>6220   | Airbus/    | 350A31-1854-21   | 37960      |              | 3000.00H | 0.00H                  |               | 3000.00H | 2758.00H          |         | 242.00H  |
| -- Spherical Thrust Bearing Bolt (#4)<br>/ Ret<br>6220   | Airbus/    | 350A31-1854-21   | 37853      |              | 3000.00H | 0.00H                  |               | 3000.00H | 2758.00H          |         | 242.00H  |
| -- Starflex Star / Ret<br>6220                           | Airbus/    | 350A31-1918-0051 | M6401      | 41656        | 3000.00H | 2106.80H<br>Nov 24, 19 | 0.00H         | 5106.80H | 651.20H<br>44.23M | 651.20H | 2348.80H |

| Main Rotor Hub - Assembly - PN: 355A31-0002-01 SN: M3496 |            |                |            |              |          |       |               |          |          |      |          |
|--|------------|----------------|------------|--------------|----------|-------|---------------|----------|----------|------|----------|
| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit    | Perf. | Time at Inst. | Due      | TTSC     | TTSN | Rem.     |
| -- Unequipped Blade Pin (#3) / Ret 6220                  | Airbus/    | 350A31-1771-21 | M27849     |              | 5000.00H | 0.00H |               | 5000.00H | 2758.00H |      | 2242.00H |
| -- Unequipped Blade Pin (#1) / Ret 6220                  | Airbus/    | 350A31-1771-21 | M27888     |              | 5000.00H | 0.00H |               | 5000.00H | 2758.00H |      | 2242.00H |
| -- Unequipped Blade Pin (#4) / Ret 6220                  | Airbus/    | 350A31-1771-21 | M27921     |              | 5000.00H | 0.00H |               | 5000.00H | 2758.00H |      | 2242.00H |
| -- Unequipped Blade Pin (#5) / Ret 6220                  | Airbus/    | 350A31-1771-21 | M28015     |              | 5000.00H | 0.00H |               | 5000.00H | 2758.00H |      | 2242.00H |
| -- Unequipped Blade Pin (#6) / Ret 6220                  | Airbus/    | 350A31-1771-21 | M28573     |              | 5000.00H | 0.00H |               | 5000.00H | 2758.00H |      | 2242.00H |
| -- Unequipped Blade Pin (#2) / Ret 6220                  | Airbus/    | 350A31-1771-21 | M27832     |              | 5000.00H | 0.00H |               | 5000.00H | 2758.00H |      | 2242.00H |
| -- Upper Sleeve Flange (#1) / Ret 6220                   | Airbus/    | 350A31-1850-03 | M22405     |              | 6600.00H | 0.00H |               | 6600.00H | 2758.00H |      | 3842.00H |
| -- Upper Sleeve Flange (#3) / Ret 6220                   | Airbus/    | 350A31-1850-03 | M22809     |              | 6600.00H | 0.00H |               | 6600.00H | 2758.00H |      | 3842.00H |
| -- Upper Sleeve Flange (#2) / Ret 6220                   | Airbus/    | 350A31-1850-03 | M22807     |              | 6600.00H | 0.00H |               | 6600.00H | 2758.00H |      | 3842.00H |

" \* " indicates that a Manual Next Due is set.

| Main Rotor Mast - Assembly - PN: 355A37-0006-00 SN: M999 |            |                |            |              |         |                       |               |          |                     |          |         |
|--|------------|----------------|------------|--------------|---------|-----------------------|---------------|----------|---------------------|----------|---------|
| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit   | Perf.                 | Time at Inst. | Due      | TTSC                | TTSN     | Rem.    |
| Main Rotor Mast / On 6230                                | Airbus/    | 355A37-0006-00 | M999       |              |         | 451.70H<br>Nov 12, 14 | 451.70H       |          | 2758.00H<br>104.63M | 3139.30H |         |
| -- 300 hr Swashplates Ch. 05-25-00 (AMM 62-              | Airbus/    |                |            |              | 300.00H | 2598.80H<br>Sep 2, 22 |               | 2898.80H | 159.20H<br>10.97M   |          | 140.80H |

Main Rotor Mast - Assembly - PN: 355A37-0006-00 SN: M999

| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit                  | Perf.                  | Time at Inst. | Due                    | TTSC                  | TTSN     | Rem.                   |
|--|------------|----------------|------------|--------------|------------------------|------------------------|---------------|------------------------|-----------------------|----------|------------------------|
| 32-00, 6-2, 6-1) /<br>Ins<br>6230  |            |                |            |              |                        |                        |               |                        |                       |          |                        |
| -- 5400 HR / 72<br>Month Main Rotor<br>Shaft (AMM 62-31-<br>00, 6-5, 6-13) / Ins<br>6230               | Airbus/    |                |            |              | 5400.00H<br>72.00M     | 2756.60H<br>Jul 25, 23 |               | 8156.60H<br>Jul 25, 29 | 1.40H<br>0.20M        |          | 5398.60H<br>71.80M     |
| -- 5400 HR / 72<br>Month Main Rotor<br>Shaft - Upper<br>Housing (AMM 62-<br>31-00, 6-14) / Ins<br>6230 | Airbus/    |                |            |              | 5400.00H<br>72.00M     | 2756.60H<br>Jul 25, 23 |               | 8156.60H<br>Jul 25, 29 | 1.40H<br>0.20M        |          | 5398.60H<br>71.80M     |
| -- Fixed scissor<br>screw / Ret<br>6230  | Airbus/    | 350A37-1146-22 |            |              | 20000.00H*             | *                      | *             | 20000.00H*             | *                     | *        | 17242.00H*             |
| -- Main Rotor Shaft<br>/ Ret<br>6220<br>Cycle Name :<br>Landings                                       | Airbus/    | 350A37-1290-04 | FR861      |              | 20000.00H<br>72000.00C | 0.00H<br>0.00C         |               | 20000.00H<br>72000.00C | 2758.00H<br>11291.00C |          | 17242.00H<br>60709.00C |
| -- Mast Lower<br>Housing / Ret<br>6230   | Airbus/    | 350A37-1292-00 | S2351      |              | 20000.00H              | 0.00H                  |               | 20000.00H              | 2758.00H              |          | 17242.00H              |
| -- Mast Upper<br>Housing / Ret<br>6230   | Airbus/    | 350A37-1291-00 | S2445      |              | 20000.00H              | 0.00H                  |               | 20000.00H              | 2758.00H              |          | 17242.00H              |
| -- MRH Attachment<br>Bolt (#1) / Ret<br>6220   | Airbus/    | 350A37-1244-20 | 84165      |              | 3000.00H               | 0.00H                  |               | 3000.00H               | 2758.00H              |          | 242.00H                |
| -- MRH Attachment<br>Bolt (#3) / Ret<br>6220   | Airbus/    | 350A37-1244-20 | 123068     | 37771        | 3000.00H               | 1387.10H<br>Feb 1, 18  |               | 4387.10H               | 1370.90H<br>66.00M    |          | 1629.10H               |
| -- MRH Attachment<br>Bolt (#2) / Ret<br>6220   | Airbus/    | 350A37-1244-20 | 131143     | 42262        | 3000.00H               | 2386.80H<br>Sep 17, 21 |               | 5386.80H               | 371.20H<br>22.47M     |          | 2628.80H               |
| -- MRH Attachment<br>Bolt (#6) / Ret<br>6220   | Airbus/    | 350A37-1244-20 | 122915     | 37770        | 3000.00H               | 1387.10H<br>Feb 1, 18  |               | 4387.10H               | 1370.90H<br>66.00M    |          | 1629.10H               |
| -- MRH Attachment<br>Bolt (#4) / Ret<br>6220   | Airbus/    | 350A37-1244-20 | 122833     | 37772        | 3000.00H               | 1387.10H<br>Feb 1, 18  | 0.00H         | 4387.10H               | 1370.90H<br>66.00M    | 1370.90H | 1629.10H               |

Main Rotor Mast - Assembly - PN: 355A37-0006-00 SN: M999

| Component/Action                       | Make/Model | Part No.                     | Serial No. | Tracking No. | Limit     | Perf.                  | Time at Inst. | Due       | TTSC               | TTSN | Rem.      |
|--|------------|------------------------------|------------|--------------|-----------|------------------------|---------------|-----------|--------------------|------|-----------|
| -- MRH Attachment Bolt (#5) / Ret 6220 | Airbus/    | 350A37-1244-20               | 122910     | 37769        | 3000.00H  | 1387.10H<br>Feb 1, 18  |               | 4387.10H  | 1370.90H<br>66.00M |      | 1629.10H  |
| -- MRH Attachment Bolt (#1) / Ret 6220 | Airbus/    | 350A37-1245-20               | 123154     | 42264        | 3000.00H  | 2386.80H<br>Sep 17, 21 |               | 5386.80H  | 371.20H<br>22.47M  |      | 2628.80H  |
| -- MRH Attachment Bolt (#3) / Ret 6220 | Airbus/    | 350A37-1245-20               | 125135     | 42263        | 3000.00H  | 2386.80H<br>Sep 17, 21 |               | 5386.80H  | 371.20H<br>22.47M  |      | 2628.80H  |
| -- MRH Attachment Bolt (#4) / Ret 6220 | Airbus/    | 350A37-1245-20               | 125204     | 42265        | 3000.00H  | 2386.80H<br>Sep 17, 21 |               | 5386.80H  | 371.20H<br>22.47M  |      | 2628.80H  |
| -- MRH Attachment Bolt (#2) / Ret 6220 | Airbus/    | 350A37-1245-20               | 81516      |              | 3000.00H  | 0.00H                  |               | 3000.00H  | 2758.00H           |      | 242.00H   |
| -- MRH Attachment Bolt (#5) / Ret 6220 | Airbus/    | 350A37-1245-20               | 116439     | 37768        | 3000.00H  | 1387.10H<br>Feb 1, 18  |               | 4387.10H  | 1370.90H<br>66.00M |      | 1629.10H  |
| -- MRH Attachment Bolt (#6) / Ret 6220 | Airbus/    | 350A37-1245-20               | 125205     | 42266        | 3000.00H  | 2386.80H<br>Sep 17, 21 |               | 5386.80H  | 371.20H<br>22.47M  |      | 2628.80H  |
| -- Non-Rotating Swashplate / Ret 6230  | Airbus/    | 350A37-1002-07               | CUR00444   |              | 20000.00H | 0.00H                  |               | 20000.00H | 2758.00H           |      | 17242.00H |
| -- Rotating Swashplate / Ret 6230      | Airbus/    | 350A37-1003-08               | CUR00429   |              | 20000.00H | 0.00H                  |               | 20000.00H | 2758.00H           |      | 17242.00H |
| -- Rotor Mast - Bearing / Ret 6230     | Airbus/    | 704A33653110/Y45RU10998S3M74 | NR8743     |              | 3000.00H  | 2756.60H<br>Jul 28, 23 |               | 5756.60H  | 1.40H<br>0.10M     |      | 2998.60H  |
| -- Scissors Drive Adapter / Ret 6230   | Airbus/    | 355A37-1235-27               | S305       |              | 20000.00H | 0.00H                  |               | 20000.00H | 2758.00H           |      | 17242.00H |
| -- Scissors Link Lower / Ret 6230      | Airbus/    | 350A37-1127-02               | SD1429     |              | 20000.00H | 0.00H                  |               | 20000.00H | 2758.00H           |      | 17242.00H |
| -- Scissors Link Lower / Ret 6230      | Airbus/    | 350A37-1127-02               | SD1729     |              | 20000.00H | 0.00H                  |               | 20000.00H | 2758.00H           |      | 17242.00H |

| Main Rotor Mast - Assembly - PN: 355A37-0006-00 SN: M999 |             |                              |            |              |           |       |               |           |          |      |           |
|--|-------------|------------------------------|------------|--------------|-----------|-------|---------------|-----------|----------|------|-----------|
| Component/Action   | Make/Model  | Part No.                     | Serial No. | Tracking No. | Limit     | Perf. | Time at Inst. | Due       | TTSC     | TTSN | Rem.      |
| -- Scissors Link Upper / Ret 6230                        | Airbus/     | 350A37-1126-02               | SD1828     |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H |      | 17242.00H |
| -- Scissors Link Upper / Ret 6230                        | Airbus/     | 350A37-1126-02               | SD1941     |              | 20000.00H | 0.00H |               | 20000.00H | 2758.00H |      | 17242.00H |
| -- Swashplate 4 Contact Bearing / Ret 6200               | Eurocopter/ | 704A33651158/Y51BB10843S2M74 | NR7900     |              | 6600.00H  | 0.00H |               | 6600.00H  | 2758.00H |      | 3842.00H  |

" \* " indicates that a Manual Next Due is set.

| Main Servocontrol (Fore/Aft) - Assembly - PN: SC8042 SN: 2701       |            |          |            |              |                     |                                 |               |                        |                                |          |                     |
|---|------------|----------|------------|--------------|---------------------|---------------------------------|---------------|------------------------|--------------------------------|----------|---------------------|
| Component/Action  | Make/Model | Part No. | Serial No. | Tracking No. | Limit               | Perf.                           | Time at Inst. | Due                    | TTSC                           | TTSN     | Rem.                |
| Main Servocontrol (Fore/Aft) / Ret 6730                             | Airbus/    | SC8042   | 2701       |              | 20000.00H           | 2106.80H<br>Nov 24, 19          | 3191.70H      | 18915.10H              | 3842.90H<br>44.23M             | 3842.90H | 16157.10H           |
| -- Main Servocontrol (Fore/Aft) / Ove 6730<br>Cycle Name : Landings | Airbus/    | SC8042   | 2701       | 38540        | 3000.00H<br>240.00M | 2106.80H<br>Nov 24, 19<br>0.00C | 0.00H         | 5106.80H<br>Nov 24, 39 | 651.20H<br>44.23M<br>11291.00C | 3842.90H | 2348.80H<br>195.77M |

" \* " indicates that a Manual Next Due is set.

| Main Servocontrol (L/H) - Assembly - PN: SC8042 SN: 3240       |            |          |            |              |                     |                                    |               |                        |                               |          |                     |
|--|------------|----------|------------|--------------|---------------------|------------------------------------|---------------|------------------------|-------------------------------|----------|---------------------|
| Component/Action   | Make/Model | Part No. | Serial No. | Tracking No. | Limit               | Perf.                              | Time at Inst. | Due                    | TTSC                          | TTSN     | Rem.                |
| Main Servocontrol (L/H) / Ret 6730                             | Airbus/    | SC8042   | 3240       |              | 20000.00H           | 2405.40H<br>Mar 31, 22             | 2560.32H      | 19845.08H              | 2912.92H<br>16.00M            | 2912.92H | 17087.08H           |
| -- Main Servocontrol (L/H) / Ove 6730<br>Cycle Name : Landings | Airbus/    | SC8042   | 3240       | 45311        | 3000.00H<br>240.00M | 2405.40H<br>Mar 31, 22<br>9736.00C | 0.00H         | 5405.40H<br>Mar 31, 42 | 352.60H<br>16.00M<br>1555.00C | 2912.92H | 2647.40H<br>224.00M |

" \* " indicates that a Manual Next Due is set.

| Main Servocontrol (R/H) - Assembly - PN: SC8043 SN: 1118 |            |          |            |              |           |                    |               |           |                     |          |           |
|--|------------|----------|------------|--------------|-----------|--------------------|---------------|-----------|---------------------|----------|-----------|
| Component/Action   | Make/Model | Part No. | Serial No. | Tracking No. | Limit     | Perf.              | Time at Inst. | Due       | TTSC                | TTSN     | Rem.      |
| Main Servocontrol (R/H) / Ret 6730                       | Airbus/    | SC8043   | 1118       |              | 20000.00H | 0.00H<br>Feb 1, 09 | 0.00H         | 20000.00H | 2758.00H<br>174.00M | 2758.00H | 17242.00H |

| Main Servocontrol (R/H) - Assembly - PN: SC8043 SN: 1118          |            |          |            |              |                     |                             |               |                       |                                  |          |                   |
|---|------------|----------|------------|--------------|---------------------|-----------------------------|---------------|-----------------------|----------------------------------|----------|-------------------|
| Component/Action  | Make/Model | Part No. | Serial No. | Tracking No. | Limit               | Perf.                       | Time at Inst. | Due                   | TTSC                             | TTSN     | Rem.              |
| -- Main Servocontrol (R/H) / Ove<br>6730<br>Cycle Name : Landings | Airbus/    | SC8043   | 1118       |              | 3000.00H<br>240.00M | 0.00H<br>Feb 1, 09<br>0.00C |               | 3000.00H<br>Feb 1, 29 | 2758.00H<br>174.00M<br>11291.00C | 2758.00H | 242.00H<br>66.00M |

" \* " indicates that a Manual Next Due is set.

| Starter Generator - Assembly - PN: 150SG122Q SN: 8733                                      |                   |           |            |              |                   |                        |               |                        |                   |          |                   |
|--|-------------------|-----------|------------|--------------|-------------------|------------------------|---------------|------------------------|-------------------|----------|-------------------|
| Component/Action   | Make/Model        | Part No.  | Serial No. | Tracking No. | Limit             | Perf.                  | Time at Inst. | Due                    | TTSC              | TTSN     | Rem.              |
| Starter Generator / Ove<br>8000  | Airbus/<br>Skurka | 150SG122Q | 8733       | 41263        | 900.00H<br>60.00M | 2030.60H<br>Aug 23, 19 | 0.00H         | 2930.60H<br>Aug 23, 24 | 727.40H<br>47.27M | 2918.60H | 172.60H<br>12.73M |
| -- Starter Generator 300 Hour<br>Inspection (SB EC130-05-026, para<br>3.B.3) / Ins<br>8000 | APC/              | 150SG122Q | 8733       |              | 300.00H           | 2756.60H<br>Jul 28, 23 |               | 3056.60H               | 1.40H<br>0.10M    |          | 298.60H           |

" \* " indicates that a Manual Next Due is set.

| Tail Rotor Blade Assembly - Assembly - PN: 350A33-3002-02 |             |                |            |              |           |                      |               |           |                     |          |          |
|---|-------------|----------------|------------|--------------|-----------|----------------------|---------------|-----------|---------------------|----------|----------|
| Component/Action  | Make/Model  | Part No.       | Serial No. | Tracking No. | Limit     | Perf.                | Time at Inst. | Due       | TTSC                | TTSN     | Rem.     |
| Tail Rotor Blade Assembly / Ret<br>6410                   | Eurocopter/ | 350A33-3002-02 |            |              |           |                      |               |           |                     |          |          |
| -- Tail Rotor Blade Assembly / Ret<br>6410                | Airbus/     | 350A33-3002-02 | M4170      |              | 10000.00H | 78.10H<br>Dec 11, 09 |               | 10078.10H | 2679.90H<br>163.67M | 2679.90H | 7320.10H |
| -- Tail Rotor Blade Assembly / Ret<br>6410                | Airbus/     | 350A33-3002-02 | M3762      |              | 10000.00H | 0.00H                |               | 10000.00H | 2758.00H            |          | 7242.00H |
| -- Tail Rotor Blade Assembly / Ret<br>6410                | Airbus/     | 350A33-3002-02 | M3789      |              | 10000.00H | 0.00H                |               | 10000.00H | 2758.00H            |          | 7242.00H |
| -- Tail Rotor Blade Assembly / Ret<br>6410                | Airbus/     | 350A33-3002-02 | M3890      |              | 10000.00H | 0.00H                |               | 10000.00H | 2758.00H            |          | 7242.00H |
| -- Tail Rotor Blade Assembly / Ret<br>6410                | Airbus/     | 350A33-3002-02 | M3899      |              | 10000.00H | 0.00H                |               | 10000.00H | 2758.00H            |          | 7242.00H |



| Tail Rotor Blade Assembly - Assembly - PN: 350A33-3002-02 |            |                |            |              |           |                       |               |           |                   |      |          |
|---|------------|----------------|------------|--------------|-----------|-----------------------|---------------|-----------|-------------------|------|----------|
| Component/Action  | Make/Model | Part No.       | Serial No. | Tracking No. | Limit     | Perf.                 | Time at Inst. | Due       | TTSC              | TTSN | Rem.     |
| -- Tail Rotor Blade Assembly / Ret 6410                   | Airbus/    | 350A33-3002-02 | M3900      |              | 10000.00H | 0.00H                 |               | 10000.00H | 2758.00H          |      | 7242.00H |
| -- Tail Rotor Blade Assembly / Ret 6410                   | Airbus/    | 350A33-3002-02 | M3920      |              | 10000.00H | 0.00H                 |               | 10000.00H | 2758.00H          |      | 7242.00H |
| -- Tail Rotor Blade Assembly / Ret 6410                   | Airbus/    | 350A33-3002-02 | M3931      |              | 10000.00H | 0.00H                 |               | 10000.00H | 2758.00H          |      | 7242.00H |
| -- Tail Rotor Blade Assembly / Ret 6410                   | Airbus/    | 350A33-3004-00 | M2888      | 42997        | 10000.00H | 2242.60H<br>Nov 2, 20 |               | 12242.60H | 515.40H<br>32.97M |      | 9484.60H |
| -- Tail Rotor Blade Assembly / Ret 6410                   | Airbus/    | 350A33-3002-02 | M3967      |              | 10000.00H | 0.00H                 |               | 10000.00H | 2758.00H          |      | 7242.00H |

" \* " indicates that a Manual Next Due is set.

| Tail Rotor Drive Shaft Asseby, EC130 - Assembly - PN: 350A34-0212-00 SN: PPT00408 |                   |                     |            |              |                    |                        |               |                        |                     |          |                    |
|---|-------------------|---------------------|------------|--------------|--------------------|------------------------|---------------|------------------------|---------------------|----------|--------------------|
| Component/Action  | Make/Model        | Part No.            | Serial No. | Tracking No. | Limit              | Perf.                  | Time at Inst. | Due                    | TTSC                | TTSN     | Rem.               |
| Tail Rotor Drive Shaft Asseby, EC130 / On 6500                                    | Airbus/           | 350A34-0212-00      | PPT00408   |              |                    | 2.30H<br>Jun 1, 09     |               |                        | 2755.70H<br>170.00M | 2755.70H |                    |
| -- 600 hr Bearing check with removal 04-20-00 / Che 6510                          | Airbus/           | 704A33651181        |            |              | 600.00H            | 2241.80H<br>Sep 25, 20 |               | 2841.80H               | 516.20H<br>34.20M   |          | 83.80H             |
| -- Aft Shaft / On 6500  | Airbus/           | 350A34-1012-05      |            |              |                    | 0.00H                  | 0.00H         |                        | 2758.00H            |          |                    |
| -- Center Shaft Section Tube Assembly (Center) / Ret 6510                         | Airbus/<br>EC 130 | 350A34-0214-00      | M1442      |              | 13200.00H          | 0.00H                  | 0.00H         | 13200.00H              | 2758.00H            |          | 10442.00H          |
| -- Front Shaft Section Assembly (Forward) / Ret 6510                              | Airbus/<br>EC 130 | 350A34-0151-00      | M1329      |              | 20000.00H          | 0.00H                  | 0.00H         | 20000.00H              | 2758.00H            |          | 17242.00H          |
| -- Tail Rotor Drive Bearing / Ret 6510  | Airbus/           | 704A33651181/593733 |            |              | 3600.00H<br>72.00M | 2241.80H<br>Sep 25, 20 |               | 5841.80H<br>Sep 25, 26 | 516.20H<br>34.20M   |          | 3083.80H<br>37.80M |

" \* " indicates that a Manual Next Due is set.

| Tail Rotor Gearbox - Assembly - PN: 350A33-0501-01 SN: M1417        |            |                |            |              |                     |                        |               |                        |                     |      |                     |
|---|------------|----------------|------------|--------------|---------------------|------------------------|---------------|------------------------|---------------------|------|---------------------|
| Component/Action  | Make/Model | Part No.       | Serial No. | Tracking No. | Limit               | Perf.                  | Time at Inst. | Due                    | TTSC                | TTSN | Rem.                |
| Tail Rotor Gearbox / Ove<br>6520                                    | Airbus/    | 350A33-0501-01 | M1417      |              | 4000.00H<br>288.00M | 0.00H<br>Feb 1, 09     |               | 4000.00H<br>Feb 1, 33  | 2758.00H<br>174.00M |      | 1242.00H<br>114.00M |
| -- 100 hr / 12 Month Tail Rotor Gearbox<br>Oil Change / Lub<br>6520 | Airbus/    |                |            |              | 100.00H<br>12.00M   | 2746.40H<br>Mar 16, 23 |               | 2846.40H<br>Mar 16, 24 | 11.60H<br>4.50M     |      | 88.40H<br>7.50M     |
| -- Bevel Pinion / Ret<br>6520                                       | Airbus/    | 350A33-5118-21 | M335       |              | 20000.00H           | 0.00H                  |               | 20000.00H              | 2758.00H            |      | 17242.00H           |
| -- Bevel Wheel / Ret<br>6520  | Airbus/    | 350A33-5111-21 | M331       |              | 20000.00H           | 0.00H                  |               | 20000.00H              | 2758.00H            |      | 17242.00H           |
| -- Control Rod Bearing / On<br>6520                                 | Airbus/    | 7050A3-6520-24 | 08363      |              |                     | 0.00H                  |               |                        | 2758.00H            |      |                     |
| -- Gear Bearing / On<br>6520  | Airbus/    | 7050A3-6520-05 | 08203      |              |                     | 0.00H                  |               |                        | 2758.00H            |      |                     |
| -- Housing Assembly / Ret<br>6520                                   | Airbus/    | 350A33-5140-01 | ML518      |              | 20000.00H           | 0.00H                  |               | 20000.00H              | 2758.00H            |      | 17242.00H           |
| -- Input Flange / Ret<br>6520                                       | Airbus/    | 350A33-5102-20 | SP407      |              | 20000.00H           | 0.00H                  |               | 20000.00H              | 2758.00H            |      | 17242.00H           |
| -- Wheel Bearing / On<br>6520                                       | Airbus/    | 7050A3-6520-04 | 08293      |              |                     | 0.00H                  |               |                        | 2758.00H            |      |                     |

" \* " indicates that a Manual Next Due is set.

| Tail Rotor Hub - Assembly - PN: 350A33-3100-01 SN: M389 |            |                |            |              |          |          |               |          |          |      |         |
|---|------------|----------------|------------|--------------|----------|----------|---------------|----------|----------|------|---------|
| Component/Action  | Make/Model | Part No.       | Serial No. | Tracking No. | Limit    | Perf.    | Time at Inst. | Due      | TTSC     | TTSN | Rem.    |
| Tail Rotor Hub / On<br>6420                             | Airbus/    | 350A33-3100-01 | M389       |              |          | 0.00H    |               |          | 2758.00H |      |         |
| -- 1200 hr Torsion Tie Bar 04-20-00 /                   | Airbus/    | 350A33-3180-01 |            |              | 1200.00H | 2405.40H |               | 3605.40H | 352.60H  |      | 847.40H |

| Tail Rotor Hub - Assembly - PN: 350A33-3100-01 SN: M389  |            |                |            |              |                    |                        |               |                        |                     |          |                    |
|--|------------|----------------|------------|--------------|--------------------|------------------------|---------------|------------------------|---------------------|----------|--------------------|
| Component/Action   | Make/Model | Part No.       | Serial No. | Tracking No. | Limit              | Perf.                  | Time at Inst. | Due                    | TTSC                | TTSN     | Rem.               |
| Che<br>6420  |            |                |            |              |                    | Mar 31, 22             |               |                        | 16.00M              |          |                    |
| -- 1800 Hr / 48 Month Thrust Screw<br>(AMM 64-21-00, 6-20) / Det<br>6421                                 | Airbus/    |                |            |              | 1800.00H<br>48.00M | 2756.60H<br>Jul 25, 23 |               | 4556.60H<br>Jul 25, 27 | 1.40H<br>0.20M      |          | 1798.60H<br>47.80M |
| -- 600 Hr / 12 Month Central Plate<br>(AMM 64-21-00, 6-22) / GVI<br>6421                                 | Airbus/    |                |            |              | 600.00H<br>12.00M  | 2756.60H<br>Jul 25, 23 |               | 3356.60H<br>Jul 25, 24 | 1.40H<br>0.20M      |          | 598.60H<br>11.80M  |
| -- 600 Hr / 12 Month Control Plate<br>Assy (AMM 64-21-00, 6-23) / GVI<br>6421                            | Airbus/    |                |            |              | 600.00H<br>12.00M  | 2756.60H<br>Jul 25, 23 |               | 3356.60H<br>Jul 25, 24 | 1.40H<br>0.20M      |          | 598.60H<br>11.80M  |
| -- 600 Hr / 12 Month Torsion tie bar-<br>to-blade attach bolt (AMM 64-21-00,<br>6-28) / GVI<br>6421      | Airbus/    |                |            |              | 600.00H<br>12.00M  | 2756.60H<br>Jul 25, 23 |               | 3356.60H<br>Jul 25, 24 | 1.40H<br>0.20M      |          | 598.60H<br>11.80M  |
| -- 600 Hr / 12 Month Torsion tie bar-<br>to-rotor hub attach bolt (AMM 64-21-<br>00, 6-29) / GVI<br>6421 | Airbus/    |                |            |              | 600.00H<br>12.00M  | 2756.60H<br>Jul 25, 23 |               | 3356.60H<br>Jul 25, 24 | 1.40H<br>0.20M      |          | 598.60H<br>11.80M  |
| -- Center Shaft Section Assembly /<br>Ret<br>6510  | Airbus/    | 350A34-0214-00 | M1442      |              | 3000.00H           | 451.70H<br>Sep 15, 14  | 451.70H       | 3000.00H               | 2758.00H<br>106.53M | 2758.00H | 242.00H            |
| -- Front Shaft Section Assembly / Ret<br>6510  | Airbus/    | 350A34-0151-00 | M1329      |              | 20000.00H          | 0.00H                  |               | 20000.00H              | 2758.00H            |          | 17242.00H          |
| -- Splined Flange / Ret<br>6420  | Airbus/    | 350A33-3141-21 |            |              | 20000.00H*         |                        | *             | 20000.00H*             | *                   | *        | 17242.00H*         |
| -- Tail Rotor Hub Assembly / Ret<br>6420   | Airbus/    | 350A33-3120-01 | CUR00227   |              | 6900.00H           | 0.00H<br>Nov 1, 08     |               | 6900.00H               | 2758.00H<br>177.00M |          | 4142.00H           |

" \* " indicates that a Manual Next Due is set.

|                                   |                      |      |
|-----------------------------------|----------------------|------|
| This report has been prepared by: |                      |      |
|                                   |                      |      |
| Signature                         | Authorization Number | Date |